## Commonwealth of Kentucky Division for Air Quality

## PERMIT APPLICATION SUMMARY FORM

Completed by: Shafiq S. Amawi

<u>Genera</u>	al Information		
	Name: Address:		General Electric Company 903 Russell Cave Pike Lexington, KY 40505-3407
	Date application receive	ed:	December 1, 1997
	SIC/Source description AFS Plant I.D.: EIS #: Application log number Permit number:		3229/glass manufacturing. 21-067-00033 102-1160-0033 F393 V-99-008
Applica	ation Type/Permit Activity  [ x ] Initial issuance  [ ] Permit modification Adminstrative Minor Significant  [ ] Permit renewal	١	<ul> <li>[ ] General permit</li> <li>[ ] Conditional major</li> <li>[ x ] Title V</li> <li>[ x ] Synthetic minor</li> <li>[ ] Operating</li> <li>[ ] Construction/operating</li> </ul>
<u>Compli</u>	ance Summary  [ ] Source is out of com [ x ] Compliance certific		[ ] Compliance schedule included
<u>Applica</u>	able Requirements list []NSR []PSD	[x]NSPS []NESHAPS	[x]SIP []Other
<u>Miscell</u>	aneous  [ ] Acid rain source [x ] Source subject to 1 [x ] Source applied for f [ ] Source provided ter [x ] Source subject to a [ ] Source requested c [ ] Application propose [x ] Certified by respons [x ] Diagrams or drawin [ ] Confidential busines	ederally enforce rms for alternativ MACT standard case-by-case 112 es new control te sible official gs included	e operating scenarios 2(g) or (j) determination

## **Emissions Summary**

Pollutant	Actual (tpy)	Potential (tpy)
PM10	150.52	176.47
SO <sub>2</sub>	46.087	46.087
NOx	567.69	567.69
СО	41.21	41.21
VOC	14.492	14.492
LEAD	0.000	0.000
HAP ≥ 10 tpy (by CAS)		

## Source Process Description:

General Electric Company (GE) produces envelopes for incandescent light bulbs. The raw materials are received in packages and bulk and are unloaded into a shuttle conveyer which transports the materials to the respective storage facilities. Once the raw materials are unloaded into the silos, conveyers transport the materials to weigh scales, a mixer, and mixer hopper where the material is weighed, mixed, and stored for inclusion into the furnace feed.

Once the raw materials are mixed in a batch process, they are fed into the furnace on a continuous basis to maintain the level of molten glass in the furnace. The furnace is a side fired, regenerative furnace which uses electric boost to aid in the melting of the glass.

The furnace has three forehearths and three process lines, each process line associated with the appropriate forehearth. Each process line consists of forming, annealing, cooling, acid etching to frost the bulbs, inspection packaging, and shipment. The forming line receives a continuous ribbon of glass and presses and blows segments of the ribbon into molds to form a bulb. The annealing consists of processing the formed bulbs through controlled heat to release any stress incurred during the forming.